

## US Army corps Of Engineers Buffalo District 1776 Niagara Street Buffalo, New York 14207-3199

## Notice to Navigation Interests

Notice No.	Date	
Waterway		

Lake Ontario, New York

**LRB-TD-ONS** 

Condition of Federal Navigation Channel Olcott Harbor, Olcott, New York

- 1. Condition surveys performed within the Federal navigation Channel at Olcott Harbor, New York during the month of July 2002 indicate shoaling has reduced depths to those shown on the attached standard tabular form and channel condition drawings.
- 2. Soundings are in feet and referred to Low Water Datum (LWD) 243.3 above Mean Water Level (MWL) at Rimouski, Quebec (International Great Lakes Datum 1985).
- 3. Vessel operators are advised to use caution when navigating in this area.
- 4. Copies of the sounding print for Olcott Harbor, New York consisting of (1) sheet, 02S-OLC-1/1, at a cost of \$2.50 per sheet will be furnished upon receipt of a check in the full amount made payable to: United States Army Engineer District, Buffalo. Requests should be addressed to: District Commander, U.S. Army Engineer District, Buffalo, ATTN: NY/PA O&M Office, 1776 Niagara Street, Buffalo, New York 14207, requesting exact number or copies of sheets by file number. A point of contact and phone number must be indicated to facilitate response to the request. To obtain the Metadata and CADD files and view a color version of this map, point your web browser to <a href="http://www.lrb.usace.army.mil/waterways/survey/survey.html">http://www.lrb.usace.army.mil/waterways/survey/survey.html</a> and locate the harbor on the table of harbors.
- 5. Buffalo district's point of contact in reference to the exact number of sheets, file number, and the availability of any later information pertaining to the area is Mr. Kelly L. Maccarone, Chief of the Survey Section, Buffalo District, and may be contacted by phone at 716-879-4285.

## REPORT OF CHANNEL CONDITIONS (FOR CHANNELS LESS THAN 400 FEET WIDE) (ER-1330-2-316)

PAGE 2 OF 4 PAGES

DATE

TO: ACCOMPANY LOCAL NOTICE TO NAVIGATION INTERESTS, DATED

FROM: U.S. ARMY CORPS OF ENGINEERS, BUFFALO DISTRICT 1776 NIAGARA STREET, BUFFALO, NY 14207-3199 (716) 879-4292 FAX (716) 879-4356

RIVER/HARBOR NAME AND STATE OLCOTT HARBOR , OLCOTT, NEW YORK					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTH WIDTH (feet)	HORIZED PRO LENGTH (feet)	DJECT DEPTH (feet)	LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
(A) ENTRANCE CHANNEL.	JULY 2002	140	1600 ( a )	12	9.6	10.0	10.6

REMARKS: (a) LENGTH VARIES DEPENDING ON THE LOCATION OF THE 12 FOOT CONTOUR IN LAKE ONTARIO, BUT IS MAINTAINED AT A DEPTH OF 10 FEET.



